

Mecklenburg County Common Code Defects

Plumbing

Code Defects

- Vent piping or air admittance valve size incorrect. (**Dry Venting**)

Code Description

DRY VENTING

905.3 Vent connection to drainage system. Every dry vent connecting to a horizontal drain shall connect above the centerline of the horizontal drainpipe.

Disclaimer: There may be other ways to comply with the Code. If so, you are not required to use this method to comply with the Code. You may want to investigate other options, or consult with a design professional identifying an equally code compliant solution.

End Notes

North Carolina Plumbing Code & North Carolina Mechanical Code & North Carolina Fuel Gas Code.
International Code Council
Southern Building Code Congress